

FORETS

Forets à centrer

Zentrierbohrer

Center drills

Punte a centrare

5

4

0


8

5



7

HSS Co5

Forets
Bohrer
Drills
Punte



60°
Forme A



OPTI
hss



Norme OPTI

540.857

D_{h7}	d_{k12}	l_1	L	Non revêtu
1	4	1.3	60	540.857-1-4-60
1	4	1.3	100	540.857-1-4-100
1.5	5	2	60	540.857-1.5-5-60
1.5	5	2	100	540.857-1.5-5-100
2	6	2.5	80	540.857-2-6-80
2	6	2.5	120	540.857-2-6-120
3	8	3.9	80	540.857-3-8-80
3	8	3.9	120	540.857-3-8-120

Gamme livrable jusqu'à épuisement du stock